



# State of Utah

## DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER  
Executive Director

### Division of Oil, Gas and Mining

JOHN R. BAZA  
Division Director

### Inspection Report Minerals Regulatory Program January 31, 2011

Reviewed:

<b>Mine Name:</b> Henefer Red Clay	<b>Permit Number:</b> M/043/0014
<b>Operator Name:</b> Interpace Holdings, LLC	<b>Inspection Date:</b> November 03, 2010
<b>Inspector(s):</b> L Heppler	<b>Time:</b> 12:15 pm
<b>Other Participants:</b> Jerry North	<b>Mine Status:</b> Active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Bond Renewal Date: 08-06-2008 Bond Amount: \$63,300 Permit fee is up to date

Purpose of Inspection: Routine annual Inspection. This site was last inspected as a large mine site on 12/04/2008 by Brett Gregory.

Inspection Summary: This site has been regraded by the Operator, which included regrading of the highwall. There is a locked gate at the entrance of the road. There is no trash or deleterious material left at this site. One road is left at this site to provide access to the north. At the time of the inspection the site had not been seeded, but left prepped and "roughened" for seeding. It is the understanding that the area was seeded after the inspection and prior to snowfall. Growth medium was mixed into the regrading of the area.

Photos were taken to document site conditions.

Conclusions and Recommendations: Good job on regrading, OGM to continue annual inspections and monitor the site when in the area to evaluate revegetation. The Division recommends release of \$46,300 for the regrading.

Inspector's Signature

LAH:eb

cc: Frank Andrews - Interpace Holdings, LLC

O:\M043-Summit\M0430014-Heneferredclay\Inspections\Insp-11032010.doc





View of regraded site (upper most disturbance) from I-80



Entrance Road



Regraded slope



Regraded slope and road to the north access